

BEST AVAILABLE COPY




Figure 1





Figure 2



BEST AVAILABLE COPY



Figure 4

	a	b	c	d	e	f	g	h	i	j
	Flat	Camber	Center buckles	Edge waves	Long centre and edge waves	Piecrust buckles	Ridges ridges	Quarter bone	Centre ridges	Herring bone
Indicated flatness profile										
Appearance of strip										
Control order										

Figure 5

BEST AVAILABLE COPY

BEST AVAILABLE COPY




Figure 6

BEST AVAILABLE COPY




Figure 7